

State of North Carolina Department of Environment, Health, and Natural Resources

Winston-Salem Regional Office

James G. Martin, Governor William W. Cobey, Jr., Secretary Margaret Plemmons Foster Regional Manager

DIVISION OF ENVIRONMENTAL MANAGEMENT GROUNDWATER SECTION

June 13, 1991

Thurston Ruder	
P&R Traile Repa	ii
2229 Bishop Rd.	
scendoro no :	77406

Dear Mr. Reader:

This letter is to acknowledge your Notification of Tank Closure as received <u>Quite 10, 1991</u> and filed as <u>Pv R Inauler Repair</u>. All future correspondence must contain the file name as well as address and county in the subject to ensure its receipt into our filing system.

The results of the required assessment (NCAC Title 15A Subchapter 2N Section .0803 and 40 CFR Part 280.72) should be submitted to this office no later than thirty (30) days after the tank is closed. If there is evidence of a release or suspected release, it must be reported within twenty-four (24) hours.

Also, please remember that to permanently close a tank, owners and operators must empty and clean it by removing all liquids and accumulated sludges as required under 15A 2N .0802 and 40 CFR 280.71(b).

Groundwater Section staff will be conducting random site visits to ensure that underground storage tank closures are conducted as required in 15A 2N .0802 and .0803 and 40 CFR 280.71 and 280.72. Any violations documented may be submitted for enforcement action.

Enclosed is an attachment that is to be used for the information required for closure assessment. You may contact me at the letterhead address or telephone number if you have any questions concerning these requirements.

Sincerely,

Thomas A. Salley

Hydrogeological Technician

TAS/ahl Enclosure

cc: WSRO

WSRO

Flow 8025 North Point Boulevard, Suite 100, Winston-Salem, N.C. 27106-3203 • Telephone 91977616325500000

(919) 896-7007 (919) 896-7005 FAX